

QUICK INSTALLATION GUIDE

Temp/humidity/co2 device (LAN-WMBUS-E2-CO2)


Recommended mounting instructions:

- Always mount on an interior wall, e.g., hallway
- The sensor works best 180cm above floor
- Mount the device so the holes at the front is on the right side
- Make sure that the UP symbol on the label (located on the side) is pointing upwards
- Avoid heating/cooling sources (solar radiation, lamps, pipes, extensive, airflow, etc.)
- Mount the device with screws

Note: Upon successful activation, the LED will flash for a couple of seconds.

Note: To verify that the device is active, hold the magnet against the label and the LED will flash until you take the magnet away again.


Note: If magnet is held for less than 5 seconds, the device will send out one packet and go back to sleep. After 25 seconds, it is possible to retry activation.



Step 1

Turn the device upside down.

Remove the mounting piece by pushing the two plastic pieces, marked by red circles, inwards and then lifting the piece up.




Step 2 (activate device):

Hold a permanent magnet against the label on device - A red LED will turn on.

Keep holding the magnet until the LED turns off (it will take about 5 seconds) When it turns off, remove the magnet.

Do not hold the magnet more than 10 second



Step 3a

Fasten the mounting piece to a wall with the text UP pointing upwards using the recommended mounting instructions.

Use two screws in the two holes filled with red in the picture.

Step 3b

Mount the device on the mounting piece. Make sure the UP symbol on the label at the side of the device is pointing upwards.

Note: The ventilation slits must be on the right side.

The installation is now complete!