

Power supply kit

PiiGAB P1 Converter

Installation guide



Installation guide for Power supply kit

Step 1:

Mount the Power supply unit next to the PiiGAB P1 Converter.

Step 2:

The supplied cable has two ends. The end with two wires is connected to the +/- terminals on the Power supply unit.

NOTE! It is important that the polarity of the cable is correct to avoid damaging the equipment.

Instructions on polarity are in the cable bag.

Step 3:

Connect the other end of the included cable, the one with an RJ12 connector, to port marked with NOT IN USE on the PiiGAB P1 Converter.

Step 4:

Connect the electricity meter to port 1 of the PiiGAB P1 Converter with an RJ12 cable (purchased separately from PiiGAB).

Step 5:

Connect the M-Bus cables that go to the M-Bus master to the M-Bus terminals on the PiiGAB P1 Converter.

